



PI-INDPED INDUSTRIAL PEDESTAL

© 2015 STONE FOREST, INC.

- Available in Cast Iron with hot wax finish
- Can be used with any vessel sink
- Use 9054D / 9053L-D Grid Drain for secure assembly
- Designed to fit most P-traps and bottle traps inside central cylinder
- Waste rough in will be approximately 21-24" from finished floor
- Approx 50 lbs.

PI-INDPED INSTALLATION DIAGRAM

Support arms should be securely mounted to the wall, either into the framing or using the supplied wall anchors into drywall.

Sink can be secured to pedestal using our 9054D or 9058D drains and the additional nut and washer supplied with the pedestal. The nut and washer thread onto the tailpiece below the sink anchor and tighten against it to secure the sink down. Additionally, a few drops of DAP Qwik-seal can be used between the sink and pedestal top.

